

## LIST OF TABLES

SERIAL NO.	LIST OF TABLES	PAGE NO.
Table 1.1	Salient Features of the Project	01-7
Table 2.1	Scoping Matrix for EIA Study for Dibang Multipurpose Project	02-9
Table 3.1	Landuse Details of Directly Draining Catchment	03-2
Table 3.2	Landuse of Submergence Area	03-4
Table 3.3	Slope Details of Directly Draining Catchment	03-4
Table 3.4	Features of R. Dibang Joining Major Tributaries (up to Dam Axis)	03-8
Table 3.5	Precipitation Data	03-10
Table 3.6	Observed Temperature and humidity data at Hunli	03-12
Table 3.7	Observed Temperature and humidity data at Elopa	03-12
Table 3.8	Categories and types of landslides encountered in the reservoir area of Dibang Multipurpose Project	03-22
Table 3.9	Description of Landslides within the Reservoir Area of Dibang Multipurpose Project	03-23
Table 3.10	Parameters of Fault Plane Solution Earthquakes	03-36
Table 3.11	Water Sampling Report	03-44
Table 3.12	Soil Details of Directly Draining Catchment	03-46
Table 3.13	Soil Sample Analysis Report	03-48
Table 3.14	Ambient Air Quality Test Report	03-53
Table 3.15	Noise Quality Analysis Report	03-54
Table 4.1	List of Gymnosperms	04-35
Table 4.2	List of Pteridophytes	04-35
Table 4.3	List of Bryophytes	04-36
Table 4.4	List of Algae	04-37
Table 4.5	List of Fungi	04-37
Table 4.6	List of Mammals	04-75
Table 4.7	List of Avi Fauna	04-77
Table 4.8	List of Snakes and other Reptiles	04-81
Table 4.9	List of Lizards	04-82
Table 4.10	List of Amphibians	04-82

Table 4.11	List of Fish	04-83
Table 4.12	List of Butterflies	04-87
Table 4.13	List of Phytoplanktons, Zooplankton and Benthos	04-88
Table 4.14	Status of Faunal Species as per Wildlife (Protection) Act, 1972	04-89
Table 4.15	Status of Faunal Species as per IUCN Red Data List 3.1	04-90
Table 4.18	Status of Fish as per National Bureau of Fish Genetic Resources	04-90
Table 5.1	Demographic Profile of Arunachal Pradesh	05-2
Table 5.2	Circle wise Demographic Details of Lower Dibang Valley	05-4
Table 5.3	Circle wise Demographic Details of Dibang Valley District	05-5
Table 5.4	Villages likely to be submerged	05-6
Table 5.5	Details of Fully Affected Villages	05-6
Table 5.6	Details of Partially Affected Villages	05-7
Table 5.7	Land Requirement for the Project	05-9
Table 5.8	Break-up of Land Requirement	05-9
Table 6.1	Calculation of Muck to be Disposed of	06-3
Table 6.2	Land required for the proposed Dibang Multipurpose Project	06-5
Table 6.3	Noise level due to operation of various construction equipment	06-16
Table 6.4	Increase in noise levels due to operation of various construction equipment	06-16
Table 6.5	Transmission loss values for various construction materials	06-17

## LIST OF MAPS

SERIAL NO.	LIST OF MAPS
Map 1.1	Layout Plan of Dibang Multipurpose Project
Map 3.1	Land use map of the directly draining catchment
Map 3.2	Land use map of submergence area
Map 3.3	Slope map of directly draining catchment
Map 3.4	Soil map of Directly Draining Catchment
Map 3.5	Land Capability Classification of Dibang Catchment
Map 3.6	Relief map of Dibang Catchment
Map 3.7	Drainage network Map of Dibang Catchment Area
Map 3.7A	Drainage Map of Directly Draining Catchment showing Submergence area
Map 3.7B	Aspect Map of Directly Draining Catchment
Map 3.8	Seismo-tectonic Map of India
Map 3.9	Sampling sites of water, soil, air and Noise
Map 6.1	Location of Wildlife Sanctuaries

## LIST OF FIGURES

SERIAL NO.	LIST OF FIGURES	PAGE NO.
Fig. 3.1	Tectonic Map of North East	03-34
Fig. 3.2	Earthquake epicentre	03-40

## LIST OF PHOTOS

<b>SERIAL NO.</b>	<b>LIST OF PHOTOS</b>	<b>PAGE NO.</b>
Photo 3.1	Feldspathic biotite gneiss outcrop on the left bank near cane-bridge, downstream of the confluence of Ichi nala with Dibang	03-19
Photo 3.2	Active landslide zone near Airi Pani confluence with Dibang river (about 2 km u/s of Dam axis)	03-27
Photo 3.3	Active landslide zone (more than 1.5 km in extent) downstream of Kronli in the rocks of Hunli Formation	03-28
Photo 3.4	Active landslide zone, left bank of Dibang at the confluence of Ithun and Dibang river	03-28
Photo 3.5	Landslides on left bank of Dibang about 1.2 km downstream of Enne nala. High rate of toe erosion and failure along weak planes has made this slide active	03-29